


User Manual



A (x1)



B (x1)



C (x1)



D (x1)



E (x1)



F (x1)



G (x1)



H (x1)



I (x5)



J (x6)
M6x25



K (x3)
M8x18



L (x4)
M6x20



M (x2)
M4x20




N (x1)
5mm




O (x1)
5mm


1




2




3






4




5



6



User Manual



A (x1)



B (x1)



C (x1)



D (x1)



E (x1)



F (x1)



I (x5)



J (x6)
M6×25



K (x3)
M8×18



L (x4)
M6×20




M (x2)
M4×20




O (x1)
5mm


1




2




3



4



5



6

